



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88670

## Inspection Report

Project Name: 5206 St. Regis Place ~ COBI

Date: 08/23/2017 Any any

Address: 5206 St. Regis Place ~ COBI, Belle Isle, Orange County, FL 32809

Permit No: 2017-06-031

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500507.0000-0115-01

Contact: Susan M & Bob Francis City Manager at 407 581 8161

Scope of Inspection: Inspection of boat dock for building & zoning compliance

Inspection Type: See Scope

Disposition of Inspection: Complete

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/23/2017	Met w/ contractor and inspected survey of dock location. No building code issues noted.	Dale Baker

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927