



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88886

Inspection Report

Project Name: 5233 Driscoll Court ~ COBI

Address: 5233 Driscoll Court ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1700308.0000-0115-01

Scope of Inspection: Roof In-Progress Inspection

Inspection Type: **See Scope**

Date: 08/25/2017 Any any

Permit No: 2017-08-056

Lot No.:

Contact: Cyndi Doyle at 407-290-6203

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489