



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86677

## Inspection Report

Project Name: 5343 Jade Circle - COBI

Date: 08/07/2017 Any any

Address: 5343 Jade Circle - COBI, Belle Isle, Orange County, FL

Permit No: 2017-08-028

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300566.0000-0115-05

Contact: Collina Gast at 407-581-8161

Scope of Inspection: REVIEW plumbing permit app for heat pump piping

Inspection Type: See Scope

Disposition of Inspection: Fail

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/07/2017	Per Dale: must provide piping schematic indicating sizes, locations, valves & fittings. FBC 107	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927