



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86924

Inspection Report

Project Name: 5700 Cove Drive ~ COBI

Address: 5700 Cove Drive ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1501272.0000-0115-02

Scope of Inspection: Final Electrical Inspection

Inspection Type: **See Scope**

Date: 08/11/2017 Any any

Permit No: 2017-04-023

Lot No.:

Contact: Nash Shook at 407.497.8767

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489