



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 87193

## Inspection Report

Project Name: 5842 Cove Drive ~ COBI

Address: 5842 Cove Drive ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600508.0000-0115-02

Scope of Inspection: Roof In-Progress Inspection

Inspection Type: See Scope

Date: 08/15/2017 Any any

Permit No: 2016-09-054

Lot No.:

Contact: J. Giles at email

Disposition of Inspection: Pass

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/14/2017	Inspection was completed previously.	Lisette Holt

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489