



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 87266

Inspection Report

Project Name:	5874 Cove Drive - COBI	Date:	08/15/2017 Any any
Address:	5874 Cove Drive, Belle Isle, Orange County, FL	Permit No:	2017-05-010
Client:	City of Belle Isle	Lot No.:	
ProjectNo.:	0115.1300234.0000-0115-06	Contact:	Rafael Valle at 321-202-0478
Scope of Inspection:	Exterior Framing Inspection for Boat Dock / Boat House		
Inspection Type:	See Scope		

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489