



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88446

## Inspection Report

Project Name: 5874 Cove Drive - COBI

Address: 5874 Cove Drive, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1300234.0000-0115-07

Scope of Inspection: Roof Sheathing Inspection for boat dock

Inspection Type: **See Scope**

Date: 08/22/2017 Any am

Permit No: 2017-05-085

Lot No.:

Contact: Rafael A. Valle at 321-202-0478

**Disposition of Inspection: Pass**

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489