



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 89036

Inspection Report

Project Name: 5874 Cove Drive - COBI

Address: 5874 Cove Drive, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1300234.0000-0115-09

Date: 08/25/2017 Any any

Permit No: 2017-08-134

Lot No.:

Contact: Susan Manchester at 407 581
8161

Scope of Inspection: REVIE W app for electrical for boat dock

Inspection Type: **See Scope**

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927