



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88473

Inspection Report

Project Name: 6115 Matchett Road ~ COBI

Date: 08/22/2017 Any any

Address: 6115 Matchett Road ~ COBI, Belle Isle, Orange County, FL

Permit No: 2017-06-015

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600455.0000-0115-04

Contact: John Reynolds at 407-709-5640

Scope of Inspection: Roof In-Progress Inspection for boat dock

Inspection Type: **See Scope**

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489