



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86308

Inspection Report

Project Name: 6504 St. Partin Place - COBI

Address: 6504 St. Partin Place - COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1300292.0000-0115-02

Date: 08/01/2017 Any any

Permit No: 2017-03-001

Lot No.:

Contact: Candace Strausheim at 407-847-9322

Scope of Inspection: Pool Safety Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489