



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88583

## Inspection Report

Project Name: 6723 Matchett Road ~ COBI

Date: 08/23/2017 Any any

Address: 6723 Matchett Road ~ COBI, Belle Isle, Orange County, FL

Permit No: 2017-01-077

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400449.0000-0115-13

Contact: Susan Manchester at 407 581  
8161

Scope of Inspection: Visit job site; replacement building permit approved back in 01/2017 however they never paid for it & no building inspections have been performed since 05/2016.

Inspection Type: **See Scope**

Disposition of Inspection: Complete

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927