



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88829

Inspection Report

Project Name: 6723 Matchett Road ~ COBI
Address: 6723 Matchett Road ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400449.0000-0115-06
Scope of Inspection: Sewer Inspection
Inspection Type: See Scope

Date: 08/25/2017 Any am
Permit No: 2016-11-032
Lot No.:
Contact: Wayne at 321-689-2747

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498