



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 89198

Inspection Report

Project Name: 7247 Lake Drive - COBI

Date: 08/30/2017 Any any

Address: 7247 Lake Drive - COBI, Belle Isle, Orange County, FL

Permit No: 2017-04-058

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300591.0000-0115-07

Contact: Jay Sherwood at 417) 880-0107

Scope of Inspection: Final Electrical Inspection for interior remodel

Inspection Type: **See Scope**

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498