



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88212

Inspection Report

Project Name: Lot 11, Bldg 13 -3556 Brighton Park Circ ~ COBI

Date: 08/18/2017 Any any

Address: Bldg 13, Lot 11 -3556 Brighton Park Circ ~ COBI, Belle Isle,
Orange County, FL

Permit No: 2017-08-043

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700013.0000-0115-06

Contact: Adlyn Rodriguez at (407) 975-
2762

Scope of Inspection: Brighton Park - Rough Mechanical Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489