



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88652

## Inspection Report

Project Name: Lot 1 - 3500 Brighton Pk Cir ~ COBI Bldg 16

Date: 08/23/2017 Any any

Address: Lot 1 - 3500 Brighton Park Circle ~ COBI, Belle Isle, Orange  
County, FL

Permit No: 2017-05-042

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700009.0000-0115-05

Contact: Angie Carroll at 321.234.0806

Scope of Inspection: Brighton Park - Final LowVoltage Inspection

Inspection Type: **See Scope**

**Disposition of Inspection: Pass**

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489