



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86758

Inspection Report

Project Name: Lot 10 Bldg 15 3548 Brighton Park Circle ~ COBI
Address: Lot 10 Bldg 15 3548 Brighton Park Circle, Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700167.0000-0115-01

Date: 08/07/2017 Any am
Permit No: 2017-04-068
Lot No.:
Contact: Jordan Dumford at (407) 607-
8303

Scope of Inspection: Brighton Park - Window Screw Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489