



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 89084

Inspection Report

Project Name: Lot 2 - 3504 Brighton Pk Cir ~ COBI Bldg 16

Date: 08/29/2017 Any am

Address: Lot 2 - 3504 Brighton Park Circle ~ COBI, Belle Isle, Orange
County, FL

Permit No: 2017-05-061

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700010.0000-0115-06

Contact: Jordan Dumford at (407) 607-
8303

Scope of Inspection: Brighton Park - Final Roof Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489