



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88650

Inspection Report

Project Name: Lot 3 - 3508 Brighton Pk Cir ~ COBI bldg 16
Address: Lot 3 - 3508 Brighton Pk Cir ~ COBI, Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700011.0000-0115-04
Scope of Inspection: Brighton Park - Final LowVoltage Inspection
Inspection Type: See Scope

Date: 08/23/2017 Any any
Permit No: 2017-05-044
Lot No.:
Contact: Angie Carroll at 321.234.0806

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489