



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 87116

Inspection Report

Project Name: Lot 45, 3553 Brighton Park Circle (Bldg 14) ~ COBI
Address: Lot 45, 3553 Brighton Park Circle (Bldg 14) ~ COBI, Belle
Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700258.0000-0115-02
Scope of Inspection: Brighton Park - Footer Steel Grounding Inspection
Inspection Type: See Scope

Date: 08/14/2017 Late pm
Permit No: 2017-08-010
Lot No.:
Contact: Bill Rose at 407-947-5125

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489