



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86278

Inspection Report

Project Name: Lot 47, 3561 Brighton Park Circle (Bldg 14) ~ COBI

Date: 07/31/2017 Any any

Address: Lot 47, 3561 Brighton Park Circle (Bldg 14) ~ COBI, Belle Isle, Orange County, FL

Permit No: 2017-08-012

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700260.0000-0115-02

Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW electrical permit app for TH

Inspection Type: See Scope

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927