



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 87058

Inspection Report

Project Name: Lot 5 Bldg 15 3528 Brighton Park Circle

Date: 08/10/2017 Any any

Address: Lot 5 Bldg 15 3528 Brighton Park Circle, Belle Isle, Orange County, FL

Permit No: 2017-08-061

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700162.0000-0115-07

Contact: Susan Manchester at 407 851 8161

Scope of Inspection: REVIEW low voltage permit app

Inspection Type: See Scope

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927