



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88904

Inspection Report

Project Name: Lot 5 Bldg 15 3528 Brighton Park Circle
Address: Lot 5 Bldg 15 3528 Brighton Park Circle, Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700162.0000-0115-01
Scope of Inspection: Brighton Park - Framing Inspection
Inspection Type: **See Scope**

Date: 08/28/2017 Any am
Permit No: 2017-04-063
Lot No.:
Contact: Jordan Dumford at (407) 607-830

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489