

## 3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

## Work Order No. 88200

<b>Inspection</b>	Report
-	-

Inspection	Type:	See Scope		
Scope of In	spection:	REVIEW app for HVAC install in new TH		
ProjectNo.: 0115.1700027.0000-0115		Contact:	Susan Manchester at 407 587 8161	
Client:	City of Bel	le Isle	Lot No.:	_
Address:	Lot 51 3581 Brighton Park Cir ~ COBI TH Bldg 12, Belle Isle, Orange County, FL		Permit No:	2017-08-102
Project Name: Lot 51 3581 Brighton Park Cir ~ COBI TH Bldg 12		Date:	08/17/2017 Any any	

## Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector:

Dale Baker, BN 3927

Jole Baker