



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88973

Inspection Report

Project Name: Lot 51 3581 Brighton Park Cir ~ COBI TH Bldg 12

Date: 08/28/2017 Any any

Address: Lot 51 3581 Brighton Park Cir ~ COBI TH Bldg 12, Belle Isle,
Orange County, FL

Permit No: 2017-01-070

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700027.0000-0115-01

Contact: John Magilson at (407) 636-0076

Scope of Inspection: Brighton Park - Window/ Door Screw Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489