



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86226

## Inspection Report

Project Name: Lot 52 3585 Brighton Park Cir ~ COBI TH Bldg 12  
Address: Lot 52 3585 Brighton Park Cir ~ COBI TH, Belle Isle, Orange  
County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1700028.0000-0115-02  
Scope of Inspection: Brighton Park - Footer Steel Grounding Inspection  
Inspection Type: See Scope

Date: 08/01/2017 Any am  
Permit No: 2017-05-023  
Lot No.:  
Contact: Bill Rose at 407-947-5125

**Disposition of Inspection:** Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489