



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88545

## Inspection Report

Project Name: Lot 6 Bldg 15 3532 Brighton Park Circle  
Address: Lot 6 Bldg 15 3532 Brighton Park Circle, Belle Isle, Orange  
County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1700163.0000-0115-03  
Scope of Inspection: Brighton Park - Rough Electrical Inspection  
Inspection Type: **See Scope**

Date: 08/23/2017 Any any  
Permit No: 2017-06-038  
Lot No.:  
Contact: Joe Thibideau at 813-955-0561

**Disposition of Inspection: Pass**

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489