



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86213

Inspection Report

Project Name: Lot 63 3709 Brighton Park Circle ~ COBI TH
Address: Lot 63 3709 Brighton Park Circle ~ COBI, Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700089.0000-0115-01
Scope of Inspection: Brighton Park - Lintel Inspection
Inspection Type: **See Scope**

Date: 08/01/2017 Any any
Permit No: 2017-03-017
Lot No.:
Contact: Ron Ring at 407-782-1471

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489